

- 2. PRELIMINARY RESULTS ON THE TEST INDICATE A PEPEAT OF YESTERDAY.
- 3. THE PILOT WAS ABLE O CORREALATE THE SYSTEM 20 LITE INDICATIONS WITH THE INTERCEPTIONS VISUALLY BECAUSE THE INTERCYPTIONS WERE CONTRAILING, AND INDICATED THAT HE DID NOT OBSERVE ANY FALSE TARGETS.

 HE COMMENTED THAT HE WAS VERY IMPRESSED WITH THE SYSTEM PERFORMANCE AND THAT DETECTION RANGES IN EXCESS OF WERE OBSERVED. 25X1DOc
 - 4. SYSTEM 20 WAS DAMAGED ON LANDING. THE RIGHT WING WAS DROPPED

Approved For Release 1999/09/07 : CIA-RDP71B0693R000200320013-9

IN 78563

2801

PAGE TWO

EVIDENTLY DUE TO A GUSTING CROSS WINDS WHICH CAUSED THE DAMAGE.

- A. THE GLASS DOME WAS BROKEN AND ADDITIONAL DAMAGE TO THE BOTTOM OF THE SYSTEM AHERE IT WAS DRAGGED ON THE RUNWAY.
- B. THE EXTENT OF DAMAGE BEYOND THIS WILL NOT BE KNOWN UNTIL THE SYSTEM CAN BE EXAMINED AT THE CONTRACTORS FACILITIES.
- C. THE SYSTEM 20 ENGINEERS ESTIMATE AT LEAST TWO TO THREE DAYS WILL BE REQUIRED FOR A DETERMINATION OF THE EXTENT OF DAMAGE.

0 5 0 0 T TOR: 080059Z DEC 67